



1998 – Lowest of 6 lock chambers



1998 – Passing water through chambers



1998 – Coating on Gate #6 was first evaluated after 1 year of service. Apparently the applicator had difficulty applying the coating and produced many areas of bubbles. In some areas the entire coating was removed perhaps with a putty knife while in other areas the tops of the bubbles were scraped off. Additional coating was applied to provide the required thickness in the repaired areas. Some of the bubbling was not repaired. Overall, no coating failures were noted and the bubbles did not appear to present any imminent concern.

