



Gate #1, CeRamKote test area at 15 months.
Dark area is mostly river scum.



Corrosion in waterline area.



Typical corrosion at waterline. No application defects were noted in this area. Damage is due to debris.



Typical corrosion observed on most ribs below the waterline area. Roughness is pitted steel.



Most severe of corrosion. No application defects were noted in this area. Damage is due to debris



Blistering was noted in several small areas. Thickness appeared normal. Cause is undefined.