



2001 Installation of piles



2001 Piles laying on deck barge



2001 Fusion bond chipped from edge



2001 Fusion bond chipped from edge



2001 Fusion bond chipped from edge



2001 Fusion bond chipped with hammer.



2001 Fusion bond poorly adhered



2001 Fusion bond damage repair.



2001 Fusion bond drips on edges.



2001 Installation. Fusion bond is green; coal tar is black.



2001 Installation of pile with vibrator.



2001 Installation. Fusion bond is green; coal tar is black.