



Railroad Bridge where test coatings were applied



Section of bridge that was not included in test



Rustbond sealer / SSPC Paint 25 / TT-P-38 applied over SP6 blasted surfaces, 7 years service



Rustbond sealer / SSPC Paint 25 / TT-P-38 applied over existing system