



MC-Zinc / MC tar / MC Luster test area



Lower pool elevation with gate closed



Erosion of MC Luster color coat



Rust due to abrasion is minimal



Erosion of MC Luster color coat