Gate #2 test area

Lower pool level with gate closed

Gate #2 test area

Gate #2 test area

Eroded edge on angle brace due to debris



Damaged edge on rib due to debris