



Railroad Bridge where test coatings were applied



Section of bridge that was not included in test



SSPC Paint 25 / TT-P-38 applied over SP5, SP6, & SP3 blasted surfaces, 7 years service.



SSPC Paint 25 / TT-P-38 applied over existing system