



District maintenance unit



Wasser test areas completed.
(MC Luster over MC Tar has a brownish appearance)



Embedment of flint abrasive



Electric airless overheated when applying zinc



Brushing of runs in MC Zinc




MC Zinc / MC Tar / MC Luster test area



MC Zinc runs in complex areas



Bubbling of 250-375 μ (10-15 mil) coating



Bubbling of 125 μ (5 mil) coating