

13 MAR 01 Storm damage to surfaces that had been pre-blasted



In protected compartments observations indicated the contractor had done an excellent job of removing the old coating. Shadows could easily have been removed in a final blast to meet the contract requirements.



Rusting was common on all exposed areas.



Rusting was common on all exposed areas.

