




Apr 01 Test area on Gate #1.



Aug 88 Steelgrip test area



Apr 90 Steelgrip test area



Apr97 Steelgrip test area



Apr 01 Steelgrip test area



Apr 01 Vinyl paint system on Gate #2 consisting of VZ-108 primer and V-106 topcoats applied the same year as test coatings on Gate #1.